


2015-2016 SLICE

Rear Brake Mount Inspection

About this Service Bulletin

It has come to our attention that some 2015-2016 Slice models may have missing rear brake mounting plate rivets. A very small number of frames may have shipped missing the rivets. The rivets are required reinforcement of the bonded brake mounts. If the rivets have not been installed in a frame, as shown below left, the frame must be replaced.



Action to Take

For the 2015-2016 Slice models listed below, please inspect any inventory that is in stock to make sure that the rivets are installed, above left. During routine service of any customer bikes, please check for the rivets on the rear brake mount. If all the rivets are in place, the bicycle is OK and no further action is required.

If the rivets are missing, see above right, please contact CSG Technical Support for information on how to obtain a warranty replacement frame. See contact information below.

2015-2016 Slice Model List

SKU	DESCRIPTION
C18106M1048	700 M Slice HM Black Inc. BLE 48
C18106M1051	700 M Slice HM Black Inc. BLE 51
C18106M1054	700 M Slice HM Black Inc. BLE 54
C18106M1057	700 M Slice HM Black Inc. BLE 57
C18106M1060	700 M Slice HM Black Inc. BLE 60
CM21104801	700 M Slice HM D/A Di2 RED 48
CM21105101	700 M Slice HM D/A Di2 RED 51
CM21105401	700 M Slice HM D/A Di2 RED 54
CM21105701	700 M Slice HM D/A Di2 RED 57
CM21106001	700 M Slice HM D/A Di2 RED 60
CM21134801	700 M Slice SM Ult Di2 REP 48
CM21135101	700 M Slice SM Ult Di2 REP 51

SKU	DESCRIPTION
CM21135401	700 M Slice SM Ult Di2 REP 54
CM21135701	700 M Slice SM Ult Di2 REP 57
CM21136001	700 M Slice SM Ult Di2 REP 60
CM21144801	700 M Slice SM Ult CRB 48
CM21145101	700 M Slice SM Ult CRB 51
CM21145401	700 M Slice SM Ult CRB 54
CM21145701	700 M Slice SM Ult CRB 57
CM21146001	700 M Slice SM Ult CRB 60
CM21244801	700 M Slice SM 105 REP 48
CM21245101	700 M Slice SM 105 REP 51
CM21245401	700 M Slice SM 105 REP 54
CM21245701	700 M Slice SM 105 REP 57
CM21246001	700 M Slice SM 105 REP 60

WARNING

Information intended for use only by Authorized Cannondale Dealers. Special tools and skills are needed. Bike Owners must not perform the work described. Serious injury or damage can result.

If you have any questions about this Service Bulletin, please call:

North America	US/Canada	1-800-BIKEUSA
	Norway	62783001
	Sweden	0844683769
Europe	Denmark	89882940
	Finland	0942451582